Approved For Release 2007762707. CHESEDF74B00499R000400950089-3

| FILE INFO | | | (W | SECRET /hen Filled In) | | cuy | CHR |
|-----------|-------|------|-------|---------------------------|-------|-----|---------|
| 14Dec 71 | 87149 | | REPRO | DUCTION PROHI | BITED | | a 3 3 £ |
| ACTION | 1 | Im | 6 | 11/025 | 11 | 16 | |
| | 2 | 1 | 7 | TOFA | 12 | 17 | |
| | 3 | 7 | 8 | | 13 | 18 | |
| | 4 | USKI | 9 | emD. | 14 | 19 | |
| | 5 | 123 | 1ø | | 15 | 2ø | |

| \$ X 1 | S | E | С | R | E, | T | 14 | Ø656 | Z | DEC | 71 | CITE | 3525 |
|---------------|----|----|----|----|----|-----|----|------|---|-----|----|------|------|
| _ | | | | | | | | | | | | | |
| | ID | ΕA | L] | SI | | -MC | 1/ | 4 | | | | | |

| 2571 | REF: | A. | |
|------|------|----|--|
| - | | В• | |

- 1. THE SNAP ACTION THERMOSTAT WAS THE CAUSE OF THE
- RFI AS REPORTED IN REF B.
 - 2. A TEST FLIGHT WITH THIS THERMOSTAT DISCONNECTED VERIFIED RFI COMING FROM THIS THERMOSTAT.
- J. THERE WAS NO OTHER RFI THAT COULD BE ATTRIBUTED TO THE "H" CONFIG.

SECRET

BT

C-361C